



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report

Supervisor DRZ

Minerals Regulatory Program
December 27, 2006

Mine Name: Courgraph
Operator Name: Howard Todd Truman
389 W 100 S
PO Box 443
Enterprise, UT 84725-0443

Permit number: M0010018
Inspection Date: 09/06/2006

Time: 2PM

Inspector(s): Tom Munson
Other Participants: Tom Faddis, Will Stokes, and John Blake
Mine Status: inactive

Weather: partly cloudy

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To determine with State Lands the status of the site and if reclamation would be required.

Directions to Site:

The site is located south of Milford on the east side of Blue Mountain close to the border of Beaver and Iron Counties.

Inspection Summary:

The site had not changed in appearance from an inspection done years previous. The site basically consists of a pad area and small highwall. State Lands sent a letter on October 30, 2006 to the Division requesting limited reclamation and that they hold a \$5,000 CD pending resolution of reclamation and lease payment issues.

Conclusions and Recommendations:

It appears that the Division needs to establish that State Lands has responsibility for ultimate reclamation through an MOU, until such time they find another responsible party. Any remaining bond money needs to be transferred to the Division.

Inspector's Signature Tom Munson

Date: 12/27/06


tm:pb

cc: Operator
Photos

O:\M001-Beaver\S0010018-courgraph\inspections\insp-09062006.doc

0002

TOPP TRUMAN COUR GRAPH S/001/018



9/6/06

S1001/008 COURGRAPH

9/6/06

